

# Contents

<b>1</b>	<b>Introduction</b>	<b>11</b>
1.1	Acceptance Sampling in Industry and Commerce . . .	11
1.2	Who Should Understand Acceptance Sampling? . . .	13
1.3	What Are Sampling Plans? . . . . .	13
1.4	Terminology . . . . .	14
1.5	What determines a sampling plan? . . . . .	15
1.6	Problems . . . . .	15
<b>2</b>	<b>Single-Stage Inspection Plans for Attributes</b>	<b>17</b>
2.1	Computing Acceptance Probabilities . . . . .	17
2.2	The Operating Characteristic (OC) Curve . . . . .	23
2.3	Designing a Sampling Plan . . . . .	25
2.4	ANSI/ASQC Z1.4 (Military Standard 105-E) Tables	27
2.5	Accept-On-Zero (AOZ) Plans . . . . .	32
2.6	Single-Stage Plans for Multiple Defects-per-Unit . .	34
2.7	Sampling Plans for Specified Producer and Consumer Risks . . . . .	35
2.8	Problems . . . . .	36
<b>3</b>	<b>Double-Stage Inspection Plans for Attributes</b>	<b>39</b>
3.1	Double-Stage Sampling Procedure . . . . .	39
3.2	Why Use Double-Stage Plans? . . . . .	39
3.3	Probability of Acceptance and OC Curves . . . . .	40
3.4	Expected Amount of Inspection . . . . .	42
3.5	ANSI/ASQC Z1.4 Tables (Mil-Std105E) . . . . .	43
3.6	Problems . . . . .	46
<b>4</b>	<b>Rectifying Sampling Plans</b>	<b>49</b>

4.1	Single-Stage Rectifying Plans . . . . .	49
4.2	Double-Stage Rectifying Plans . . . . .	53
4.3	Problems . . . . .	59
<b>5</b>	<b>Inspection Plans for Variables</b>	<b>61</b>
5.1	Example: Organic Milk Distribution . . . . .	62
5.2	Specification Limits . . . . .	62
5.3	Procedure . . . . .	62
5.4	The Normality Assumption . . . . .	63
5.5	Known vs. Unknown Process Standard Deviation .	64
5.6	k-Method: Distance of Sample Mean from Specifica- tion Limit . . . . .	66
5.7	M-Method: Limit on Proportion of Non-Conforming Items . . . . .	68
5.8	ANSI/ASQC Z1.9 Tables (Military Standard 414) .	70
5.9	Sampling Plans for Specified Producer and Consumer Risks . . . . .	79
5.10	Problems . . . . .	81
<b>6</b>	<b>Continuous Sampling</b>	<b>85</b>
6.1	Continuous Sampling Plan 1 (CSP-1) . . . . .	86
6.2	Continuous Sampling Plan 2 (CSP-2) . . . . .	91
6.3	Mil-Std-1235 Tables . . . . .	92
6.4	Online Plans . . . . .	95
6.5	Skip-Lot Sampling Plans . . . . .	97
6.6	Problems . . . . .	101